## 100/200/300/400 USB OUTPUT INTERFACE

VIDEO

100-11

◆ The cable without software, push the black button or footswitch, the data can be transferred into Excel, Word directly.

◆ The cable with software, the data can be transferred into the software at a set interval time automatically.

Connect foot switch to transfer the data
(code: **400-01**)

Software

0.5m   2m
0.5m   2m
0.5m   2m

computer

Code	Software	Plug to product	Products
100-03	Without		for digital calipers with following electronics
100-04	With		*
100-03L	Without	8mm	for digital height gage with following electronics
100-04L	With		*
100-11	Without		for digital calipers with following electronics
100-12	With		
100-15	Without		for digital calipers and height gage with following electronics
100-17	Without		for digital calipers with following electronics

Code	Software	Plug to product	Products
200-03	Without		for digital indicators with following electronics
200-04	With		
200-01	Without		for digital indicators with following electronics
200-02	With		
200-05	Without		for digital indicators with following electronics (output radius)
200-06	With		
300-03	Without		for digital micrometers with data output with following electronics
300-04	With		

Code	Name
400-01	foot switcht

* Confirm the electronics output port type when placing orders