100/200/300/400


USB OUTPUT INTERFACE






- The cable without software, push the black button or footswitch, the data can be transferred into Excel, Word directly.
- The cable with software, the data can be transferred into the software at a set interval time automatically.

Connect foot switch to transfer the data (code: **400-01**)



Software



Real-time measurement	Auto Start	mual	Ma	Save		Clear
0.000 mm		n	collection	- Data c		
U. UUU IIIII	Time	I	Result	Error	Value	No
	-23 10:27:13		NG	-1.000	0.000	000001
	-23 10:27:14		NG	-0.100	0.900	000002
	-23 10:27:15		OK	2.470	3.470	000003
Disconnect Zero	-23 10:27:16		OK	5.150	6.150	000004
ASC	-23 10:27:17		NG	7.730	8.730	000005
	-23 10:27:18		NG	11.370	12.370	000006
Real-time statistics	-23 10:27:19		NG	14.310	15.310	000007
VedT_(TWe std(IstIns	-23 10:27:20		NG	18.330	19.330	800000
AVG 8,82294 Num 17 NG+ 6	-23 10:27:21		NG	20.250	21.250	000009
AVG 8.82294 Num 17 NG+ 6	-23 10:27:22		NG	22.600	23.600	000010
	-23 10:27:27		OK	5.810	6.810	000011
MAX 23.6 OK 9 NG- 2	-23 10:27:28		OK	5.450	6.450	000012
, , , , , , , , , , , , , , , , , , , ,	-23 10:27:29		OK	5.100	6.100	000013
MIN O	-23 10:27:30		OK	4.680	5.680	000014
MIN JO	-23 10:27:31	2024-08-2	OK	4.130	5.130	000015
	-23 10:27:31		OK	3.510	4.510	000016
Parameters	-23 10:27:32	2024-08-2	OK	3. 200	4.200	000017
STD Beep off Auto 20						
USL 6 Unit mm - period Ms						
our land						
LSL I						
Parameters						

Code	Software	Plug to product	Products
Code	Software	Flug to product	Floudets
100-03	Without	(*****)	for digital calipers with following electronics
100-04	With	The state of the s	**************************************
100-03L	Without	()	for digital height gage with following electronics
100-04L	With	8mm	-0
100-11	Without	THE MAN S	for digital calipers with following electronics
100-12	With		1113
100-15	Without		for digital calipers and height gage with following electronics
100-17	Without	170000	for digital calipers with following electronics

_	
s	300-03
th	300-04
3	
	Code
	400-01
ers	

Code	Software	Plug to product	Products
200-03	Without	(for digital indicators with following electronics
200-04	With	The state of the s	200
200-01	Without		for digital indicators with following electronics
200-02	With		
200-05	Without		for digital indicators with following electronics
200-06	With	The state of the s	(output radius)
300-03	Without	- Marie Mari	for digital micrometers with data output with following electronics
300-04	With	7	25.425
			_

Name

foot switcht

^{*}Confirm the electronics output port type when placing orders